

# DigiLink DLC100 - Optical Transmitter, Receiver, Transceiver, or Repeater for HD-SDI, SD-SDI, SDTI, DVB-ASI, and ATSC

## Artel ships the DLC100 configured as follows:



- All signal types allowed
- Electrical input set to BNC
- EMS override is enabled (EMS can change the DLC100 configuration)

## **Mode Switch Configurations**

Setting	DLC100 Module	<b>Electrical Signal</b>		Optical Signal	
		IN	OUT	RX	TX
RECEIVE	Receives optical signals only. The SFP laser used to transmit signals is turned off and the transmit alarms are disabled.		х	X	
TRANSMIT	Transmits signals only. The SFP receiver is disabled and the receive alarms are disabled.	Х			Х
TRANSCEIVE	Receives and transmits signals. The SFP laser and receiver are enabled as are the associated alarms.	Х	Х	X	Х
REPEATER	Reclocks the received optical signal and transmits the signal back out. The optical receive signal is also available on the electrical outputs.		X	X	Х

#### Factory Default: Transceive

# **DIP Switch Configurations**

SW1 Configuration			
<b>S1</b>	S1 S2 Receive Mode		
On	On	Auto	
On	Off	SD	
Off	On	HD	
Off	Off	Bypass	

<b>S</b> 3	<b>S4</b>	Transmit Mode	
On	On	Auto	
On	Off	SD	
Off	On	HD	
Off	Off	Bypass	

<b>S5</b>	<b>S6</b>	<b>S7</b>	Input Source	
On	On	On	BNC In	
Off	Off	Off	Backplane 1	
Off	On	Off	Backplane 2	
Off	Off	On	Backplane 3	
Off	On	On	Backplane 4	

	Function	Off	On	
S8	EMS	Local	Remote	
30	Override	Control	Control	

Factory Default: All On





### **Install SFP**



LED	Function	Color	Description			
		OFF	If power is applied to the system, an internal fault with the DLC100 may exist			
OK	DLC100	Green	Normal operation			
	Module Status	Yellow	If the RX LED is not flashing yellow, then a temperature alarm is indicated			
	Status	Red	The TX or RX LEDs may indicate the cause of the alarm or the alarm condition can indicate an internal error			
EMS	DigiLink Manager System Status	OFF	The DLC100 module is in local mode and its configuration is controlled by the onboard configuration switches			
		Green	The DLC100 module is in remote mode and the configuration has been set by the EMS. When in remote mode, the actual configuration of the module will likely not match the settings of the configuration switches and changing the configuration switches will have no effect on the module's operation			
		OFF	Transmitter is disabled. The DLC100 is in receiver-only operating mode			
		Green	Normal operation (input signal is present)			
		<b>*</b> Green	No SFP is installed (RX and TX LEDs are both flashing) or an SFP TX failure exists			
TX		Yellow	The DLC100 cannot detect an input signal and is transmitting the standby signal			
	Transmitter Status	* Yellow	No SFP is installed (RX and TX LEDs are both flashing) or an optical SFP TX failure exists.  Also, the DLC100 cannot detect an input signal and is transmitting the standby signal			
	Status	Red	The DLC100 detects an incorrect input signal type. For example, you have the DLC100 configured to receive 270 Mb/s signal rates only, but another signal rate is received			
		* Red	No SFP is installed (RX and TX LEDs are both flashing) or an SFP TX failure exists. Also, the DLC100 detects an incorrect input signal rate. For example, you have the DLC100 configured to receive 270 Mb/s signal rates only, but another signal rate is received			
		OFF	270 Mb/s signal			
HD	Transmitter Rate	Green	1.485 Gb/s or 1.485/1.001 Gb/s signal (uncompressed HD)			
	Status	Yellow	19.39 Mb/s signal detected (ATSC HD or other signal rate)			
		OFF	Repeater mode disabled			
RPTR	Repeater Mode Status	Green	Repeater mode enabled (optical output = optical input)			
	Receiver Mode Status	OFF	Receiver is disabled. The DLC100 is in transmit-only operating mode			
RX		Green	Normal operation (receiver signal is present)			
		Yellow	Standby signal is being received from the transmitter			
		* Yellow	Receive optical power is high			
		Red	The DLC100 detects an incorrect input signal type. For example, you have the DLC100 configured to receive 270 Mb/s signal rates only, but another signal rate is received			
		* Red	No SFP is installed (RX and TX LEDs are both flashing), a low receiver power condition exists, or an SFP RX failure exists			
		OFF	270 Mb/s signal			
HD	Receiver Rate	Green	1.485 Gb/s or 1.485/1.001 Gb/s signal (uncompressed HD)			
-		Yellow	19.39 Mb/s signal (ATSC HD) or other signal rate			

<sup>\*</sup>Flashing green | \*Flashing yellow | \* Flashing red

Sales



T: 978-263-5775 www.artel.com sales@artel.com customercare@artel.com