

InfinityLink ILC274D - SD-SDI, ASI Digital Video 4 Ch TDM De-Multiplexer

Artel ships the ILC274D configured as follows:

- All four channels enabled
- No video detected alarm disabled
- EMS override enabled (IL Manager can change the ILC274D configuration)

■ DIP SWITCH CONFIGURATIONS

SW1 Configuration				
SW1	Function	Off	On	
S1	Ch A Operation	Disabled	Normal Operation	
S2	Ch B Operation	Disabled	Normal Operation	
S3	Ch C Operation	Disabled	Normal Operation	
S4	Ch D Operation	Disabled	Normal Operation	
S5	Optical TX Disable	Repeater Operation	Disables transmitter/ repeater	
S6	Video Alarm Disable	Alarm on video loss	No alarm on video loss	
S7	Reserved	-	Must be On	
S8	EMS Override	Local Control	RemoteControl	

Factory Default: All On



Configuration Switch Functions

SW1 Controls the channel (A, B, C and D) output operation, enabling/disabling of the optical TX (repeater) operation, controls the loss of video alarm option, and enables the EMS over ride function.



Install SFP



DLC274D FRONT PANEL LEDS

LED	Function	Color	Description	
ок	ILC274D Module Status	OFF	If power is applied to the system, an internal fault with the ILC274D may exist	
		Green	Normal operation	
		Yellow	If no other status LEDs indicate a minor alarm, then a temperature alarm is indicated	
		Red	If no other status LEDs indicate a major alarm, then an internal error is indicated, such as an onboard communications error or an onboard power error	
EMS	IL Manager System Status	OFF	The ILC274D module is in local mode and its configuration is controlled by the onboard configuration switches	
		Green	The ILC274D module is in remote mode and the configuration has been set by the EMS. When in remote mode, the actual configuration of the module will likely not match the settings of the configuration switches and changing the configuration switches will have no effect on the module operation	
ТХ	Transmitter Status	OFF	Transmitter is disabled	
		Green	Normal operation (repeating input signal)	
		Red	SFP TX failure exists	
		* Red	No SFP is installed	
RX	Receiver Status	Green	Normal operation	
		Yellow	Link errors detected	
		* Yellow	Receive optical power is high	
		Red	No input signal or the input signal type is incorrect (not a valid ILC274M or ILC274M signal)	
		* Red	Possible causes: • A low receiver power condition exists • No SFP is installed • An SFP RX failure exists	
A, B, C, D	270 Mb/s Channel Status	OFF	Channel is disabled on the ILC274D or ILC274M	
		Green	270 Mb/s video detected	
		Yellow	No signal to the ILC274M	
		Red	Video input signal rate is outside the range (270 Mb +/- 100 ppm)	

* Flashing yellow | * Flashing red

Sales



T: 978-263-5775 www.artel.com sales@artel.com customercare@artel.com