

Release Note

Date:	1/4/02	Model(s)	DigiLink 2701 (DL2701)
--------------	--------	-----------------	------------------------

Corrections to Product Manual

The following information is listed incorrectly in the *DigiLink 2701 Installation and Operation Guide* (P/N 200-000691-00 rev: A). This information will be corrected in the next release of the manual.

Temp High LED information incorrect in product manual

The color of the TEMP HIGH LED—located on the front panel of both the DL2701 encoder and DL2701 decoder—is yellow, not red as stated in manual. This LED is used to indicate that the internal system temperature limit has been exceeded, which is a minor alarm condition.


The following tables in the manual contain information related to this LED and will be updated with the correct information on the next release:

- Table 3-3, page 3-10
- Table 4-3, page 4-9


DL2701 Decoder has two, not one, ASI/SDI output ports

The manual currently describes the DL2701 decoder as having only one ASI/SDI output port located on the rear panel. This product has two such ports with identical specifications as shown in the following corrected illustrations:

- Rear panel view (Figure 4-2, page 4-3)



- Block diagram (Figure 1-1, page 1-7)



Heat load values incorrect

The following changes are required to the heat load information found on page 2-5:

	Power Dissipation	Approx. BTU/hr
Incorrect Values Listed	55 W	190
Correct Values	<25 W	85

Contact Artel

Contact Artel's Technical Support department should you have any questions concerning the content of this document.

- 1 800 225-0228 (USA)
- (508) 303-8200 (outside USA)